

2000-3  
Kodiak

ORIGINAL

Sheet 1 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)

KONIAG, INCORPORATED

AT  
KARLUK, ALASKA

AND  
THE DEPENDENT RESURVEY OF  
U.S. SURVEY NO. 469, TRACTS A AND B,  
U.S. SURVEY NO. 2030,  
KARLUK SUBDIVISION TRACT F (SCHOOL),  
AND PORTIONS OF  
U.S. SURVEY NOS. 44, 162, 1454, 2006  
AND KARLUK SUBDIVISION

This plat contains the entire record.

This survey was executed by Marshal D. Wade, Cadastral Surveyor, April 22 through May 13, 1998, in accordance with the principles set forth in the Manual of Surveying Instructions, 1973; Special Instructions approved November 26, 1997; the Karluk ANCSA 14(c) Map of Boundaries, accepted September 12, 1996, and Assignment Instructions dated April 16, 1998.

Field assistants were:

Craig S. Dukart, Land Surveyor  
Michael O. Harmening, Land Surveyor  
Christopher D. Wiita, Land Surveyor

Area: 1,294.17 Acres.

The azimuth was obtained with the Global Positioning System (GPS), using static relative and real-time-kinematic (RTK) positioning techniques, and refers to the true meridian.

The geographic position of the northerly Airport Access Road right of way corner, at intersection with Tracts C and G, as determined from a tie to BLM "GEO STA 60208 1979", is:

Latitude: 57° 33' 49.67" North

NAD 27

Longitude: 154° 26' 29.20" West

All distances and areas as shown on this plat, sheets 1 through 8, are in U.S. survey feet and acres, respectively.

The mean magnetic declination was observed during the execution of this survey.

This survey is situated in and around the village of Karluk, within Township 30 South, Range 32 West, Seward Meridian, Alaska.

The land is open and rolling, surrounded by mountains on either side of the Karluk River valley, with scattered alder and willow patches.


The soil is primarily volcanic ash, loam and some clay.

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Anchorage, Alaska

The survey represented by this plat, Sheets 1-8, having been properly executed and examined, is hereby accepted for having fulfilled the requirements of Section 14(c) of the Alaska Native Claims Settlement Act.

For the Director

*Barry L. Pinkerton* JANUARY 27, 2000  
Deputy State Director for Cadastral Survey, Alaska  
Acting



# HISTORY OF SURVEYS

U.S. Survey No. 44 was surveyed by T.J. Dewoody, U.S. Deputy Surveyor, in 1892, cancelled in 1921, reinstated in 1983, and dependently resurveyed by David M. Klein and Marshal D. Wade, Cadastral Surveyors, in 1997.

U.S. Survey No. 162 was surveyed by Clinton Gurnee, Jr., U.S. Deputy Surveyor, in 1899, and dependently resurveyed by Tommy A. Noble, David M. Klein and Marshal D. Wade, Cadastral Surveyors, in 1981-1998.

The survey of the median line of a portion of the relicited channel of the Karluk River was surveyed by David M. Klein and Marshal D. Wade, Cadastral Surveyors, in 1997.

U.S. Survey No. 469, Tracts A and B, was surveyed by Frank H. Lacey, U.S. Deputy Surveyor, in 1905.

U.S. Survey No. 1454 was surveyed by Harold H. Waller, U.S. Deputy Surveyor, in 1922.

U.S. Survey No. 2006 was surveyed by Charles S. Hubbell, U.S. Deputy Surveyor, in 1930, and a portion was dependently resurveyed by Marshal D. Wade, Cadastral Surveyor, in 1998.

U.S. Survey No. 2030 was surveyed by Floyd G. Betts, U.S. Cadastral Engineer, in 1931.


Karluk Subdivision was surveyed by Roy A. Ecklund, Alaska Registered Land Surveyor No. 1638, in 1978, and filed as plat No. 78-16 in the Kodiak Recording District, Alaska, on July 13, 1978.

Karluk Subdivision, Tract F (School), was surveyed by Roy A. Ecklund, Alaska Registered Land Surveyor No. 1638, in 1982, and filed as plat No. 82-13 in the Kodiak Recording District, Alaska, on June 16, 1982.

The Karluk Airport Property Plan was surveyed by the State of Alaska Department of Transportation and Public Facilities in 1973, with numerous subsequent revisions. No plat was filed.

Robert L. Tarrant, Alaska Registered Land Surveyor No. 1641, remonumented corner No. 5, U.S. Survey No. 2006, in 1981. No record was filed.

COPY



I hereby certify that Tracts A through H and the airport access road, represented on this plat of survey are on lands Interim Conveyed to Koniag, Incorporated, by Interim Conveyance No. 105 issued by the United States of America; said road and tracts also fulfill all entitlements under the provisions of ANCSA 14(c) as requested by Koniag, Incorporated Board of Resolution No. 96-05, and the Karluk ANCSA 14(c) Map of Boundaries, accepted September 12, 1996.

1/25/2000  
Date  
*Barry L. Pinkerton*  
President, Koniag Incorporated

I, Marshal D. Wade, Cadastral Surveyor, HEREBY CERTIFY upon honor that I have executed the ANCSA 14(c) survey depicted on this plat, Sheets 1-8, in conformity with the Special Instructions approved November 26, 1997, the principles of survey described in the Manual of Surveying Instructions, 1973, and in the specific manner described on this plat.

1/21/2000  
Date  
*Marshal D. Wade*  
Cadastral Surveyor

MDW

ME

2000-3

Kodiak

ORIGINAL

Sheet 2 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)


KONIAG, INCORPORATED  
AT  
KARLUK, ALASKA

REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

## LEGEND

- Set a stainless steel post, 2 1/2 ins. diam., 28 ins. long, with brass cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, and adjoining survey lines and numbers. Witness points and witness corner to meander corners have additional marks WP and WC MC respectively. Refer to Monument and Accessory table for accessories established at each monument. Deposit a magnet in a white plastic case at the base of each stainless steel post.

- BLM corner recovered this survey.



This cor. is determined at the orig. glass memorial; no remaining evidence of the orig. iron pipe.

The original pits 24 x 18 x 4 ins., SE, on line, 5 ft. dist. and 24 x 24 x 6 ins., SW, on line, 4 1/2 ft. dist.

No remaining evidence of the original mound of earth.

At the corner point, set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 27 ins. in the ground, with brass cap mkd. as shown.

Rehabilitate the original pits to now measure 24 x 24 x 12 ins.

Drive a steel fence post, 6 ft. long, 3 ft. in the ground, 3 ft. N of cor.

Deposit the original glass and a magnet in a white plastic case at the base of the stainless steel post.

Found an iron pipe, 3 1/2 ins. diam., firmly set, projecting 18 ins. above ground, nearly rusted through at ground level, with punch marks R.G.C.K. TB. Cor. 2 on the NE side, and a firebrick at the base of the pipe.

The original pits, 24 x 24 x 6 ins., SW on line 5 1/2 ft. dist., and 24 x 24 x 8 ins., NW on line, 6 ft. dist.

No remaining evidence of the original mound of earth.

At the corner point, set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 27 ins. in the ground, with brass cap mkd. as shown.

Bury the original iron pipe, inverted on the west side of the stainless steel post.

Rehabilitate the original pits to now measure 24 x 24 x 12 ins.

Deposit the original pieces of fire brick and a magnet in a white plastic case at the base of the stainless steel post.

Found an iron pipe, 3 1/2 ins. diam., firmly set, projecting 12 ins. above ground, with punch marks R.G.C.K. TB. COR. 3 on the N side.

The original mound of earth, 3 ft. base, 1 ft. high, 2 ft. N of cor.

No remaining evidence of the original pits.

Drive a steel fence post, 6 ft. long, 3 ft. in the ground, 3 ft. S of cor.

Found an iron pipe, 3 1/2 ins. diam., firmly set, projecting 12 ins. above ground, with punch marks R.G.C.K. TB. Cor. 4 on the E side.


No remaining evidence of the original pits or mound of earth.

No new accessories taken.

## MONUMENT AND ACCESSORY TABLE

MONUMENT	DEPTH	ACCESSORY TYPE	DEPTH	BASE	HEIGHT	DIRECTION	DISTANCE
E	27"	MOUND OF STONE		2 1/2 FT.	1 1/2 FT.	NORTHEAST	ALONGSIDE
F	26"	LOCATED NEAR A SPRING					
G	26"	NONE AVAILABLE					
H	24"	MOUND OF STONE		3 FT.	2 FT.	NORTH	ALONGSIDE
I	26"	STEEL FENCE POST	3 FT.			SOUTH	3 FT.
J	27"	STEEL FENCE POST	3 FT.			SOUTH	3 FT.
K	27"	STEEL FENCE POST	3 FT.			SOUTH	3 FT.

COPY



2000-3  
Kodiak

ORIGINAL

Sheet 3 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)

KONIAG, INCORPORATED  
AT  
KARLUK, ALASKA

REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

TRACT A  
SEE SHEET No. 2

TRACT B


U.S.S.  
1454

LEGEND

- Set a rebar, 5/8 in. diam., 30 ins. long, with aluminum cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, easement centerlines and adjoining survey lines and numbers. Witness corner to meander corners have additional marks WC MC. No accessories taken.

- ⊙ BLM corner recovered this survey. See sheet No. 2 for recovery information.

NOTE:  
The seasonal creek segregating Lots 2 and 7 from Lots 3 and 6 is measured to the thread and is an ambulatory boundary. The water line easement is also ambulatory, centered on the thread of the creek.



MEANDERS TRACT B

Along a well-defined bank,  
at the line of mean high tide.

LOT 1	LOT 7
1. N. 76°52' W., 75.99 ft.	1. N. 73°38' W., 80.05 ft.
2. N. 73°38' W., 60.00 ft.	
LOT 4	LOT 8
1. N. 31°35' W., 54.52 ft.	1. N. 47°57' W., 76.77 ft.
	2. N. 76°52' W., 44.42 ft.
LOT 5	LOT 10
1. N. 31°35' W., 96.59 ft.	1. N. 47°57' W., 109.85 ft.
2. N. 22°16' W., 89.12 ft.	
LOT 6	LOT 12
1. N. 73°38' W., 71.06 ft.	1. N. 32°25' W., 112.26 ft.
2. N. 31°35' W., 128.02 ft.	2. N. 47°57' W., 18.49 ft.

DETAIL

COPY

2000-3  
Kodiak

ORIGINAL

Sheet 4 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)

KONIAG, INCORPORATED  
AT  
KARLUK, ALASKA

REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

MEANDERS TRACT C

Along a well-defined bank,  
at the line of mean high tide.

1. S. 88°03' W. 11.14 ft.
2. S. 75°41' W. 90.51 ft.
3. N. 77°22' W. 155.51 ft.
4. N. 57°04' W. 369.71 ft.
5. N. 37°07' W. 315.44 ft.
6. N. 60°37' W. 138.11 ft.
7. N. 83°11' W. 113.73 ft.
8. S. 79°20' W. 270.02 ft.
9. S. 82°34' W. 172.92 ft.
10. S. 61°07' W. 180.00 ft.
11. S. 77°57' W. 163.81 ft.
12. S. 66°57' W. 350.46 ft.
13. S. 82°41' W. 265.84 ft.
14. S. 73°48' W. 206.69 ft.
15. S. 60°50' W. 96.22 ft.
16. N. 51°38' W. 142.26 ft.
17. S. 84°35' W. 39.91 ft.
18. N. 18°59' W. 162.83 ft.

Along a well-defined bank,  
at the line of ordinary high water.

19. S. 18°36' E. 21.73 ft.
20. S. 30°23' W. 140.91 ft.
21. S. 72°57' W. 112.20 ft.
22. S. 87°56' W. 442.01 ft.
23. S. 84°00' W. 318.49 ft.
24. N. 79°04' W. 203.63 ft.

B.L.M.  
"GEO STA 60208 1979"  
Lat. 57°34'36.737" N.  
Long. 154°26'16.092" W.  
(NAD27)

SEE SHEET No. 2

KARLUK  
LAGOON

KARLUK SUBDIVISION  
PLAT No. 78-16

SEE SHEET No. 5



KARLUK SUBDIVISION  
TRACT F (SCHOOL)  
PLAT No. 82-13

TRACT C  
711.47


LEGEND

- Set a stainless steel post, 2 1/2 ins. diam., 28 ins. long, with brass cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, and adjoining survey lines and numbers. Witness points and witness corner to meander corners have additional marks WP and WC MC respectively. Refer to Monument and Accessory table for accessories established at each monument. Deposit a magnet in a white plastic case at the base of each stainless steel post.


- BLM corner recovered this survey.




Found a stainless steel post, 2 1/2 ins. diam., firmly set, flush with the ground, with brass cap mkd. as shown.  
No original accessories of record, no accessories taken.



Found a stainless steel post, 2 1/2 ins. diam., firmly set, projecting 2 ins. above the ground, with brass cap mkd. as shown.  
The original mound of stone, 3 ft. base, 1 1/2 ft. high, south of the cor., alongside.




Found a stainless steel post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd. as shown.  
The original mound of stone, 3 ft. base, 1 1/2 ft. high, south of the witness cor., alongside.



Found a stainless steel post, 2 1/2 ins. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd. as shown.  
The original pits, 18 x 18 x 12 ins., N. 28° E., 5.3 ft. dist., and S. 62° E., 4.6 ft. dist.

COPY



MONUMENT AND ACCESSORY TABLE

MONUMENT	DEPTH	ACCESSORY TYPE	DEPTH	BASE	HEIGHT	DIRECTION	DISTANCE
T	28"	STEEL FENCE POST	3 FT.			S. 61°59' E.	3 FT.
U	24"	MOUND OF STONE IN PLACE	4 FT.	2 FT.		NORTH	ALONGSIDE
V	14"	MOUND OF STONE		5 FT.	14 INS.	ENCIRCLING MONUMENT	
W	20"	MOUND OF STONE IN PLACE	5 FT.	2 FT.		NE	4 1/2 FT.
X	22"	MOUND OF STONE	4 FT.	1 FT.		ENCIRCLING MONUMENT	
Y	20"	MOUND OF STONE	5 FT.	1 FT.		ENCIRCLING MONUMENT	
Z	24"	MOUND OF STONE	4 FT.	1 1/2 FT.		NORTH	ALONGSIDE
AI	28"	STEEL FENCE POST	3 FT.			NORTH	4 FT.
BI	27"	STEEL FENCE POST	3 FT.			NORTH	3 FT.
CI	27"	STEEL FENCE POST	3 FT.			SOUTH	3 FT.

2000-3  
Kodiak

ORIGINAL

Sheet 5 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)

KONIAG, INCORPORATED  
AT  
KARLUK, ALASKA


REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

LEGEND


- Set a rebar, 5/8 in. diam., 30 ins. long, with aluminum cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, lot and block lines, right of way lines, road names and adjoining survey lines and numbers. No accessories taken.
- ⊗ Set a rebar, 5/8 in. diam., 30 ins. long, with aluminum cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, lot and block lines, right of way lines, road names and adjoining survey lines and numbers, at proportionate position. No accessories taken.
- 2 1/2 in. diam. alum. pipe, with alum. cap recovered this survey.
- 5/8 in. diam. rebar with alum. cap recovered this survey.

MEANDERS

- Along a well-defined bank,  
at the line of mean high tide.
- 1. S. 60°50' E., 104.96 ft.
  - 2. S. 62°30' E., 214.88 ft.
  - 3. S. 72°44' E., 148.09 ft.
  - 4. S. 82°39' E., 165.70 ft.
  - 5. S. 68°22' E., 108.77 ft.
  - 6. S. 58°28' E., 102.86 ft.
  - 7. S. 67°23' E., 130.28 ft.
  - 8. S. 58°35' E., 83.40 ft.



COPY





2000-3  
Kodiak

ORIGINAL

Sheet 6 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)

KONIAG, INCORPORATED

AT  
KARLUK, ALASKA

REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

MONUMENT AND ACCESSORY TABLE

MONUMENT	DEPTH	ACCESSORY TYPE	DEPTH	BASE	HEIGHT	DIRECTION	DISTANCE
KI	27"	3 IN. WOODEN POLE	3 FT.	7 1/2 FT. LONG		SOUTH	3 FT.
LI	27"	STEEL FENCE POST	3 FT.			WEST	3 FT.
MI	27"	2 PITS		10 X 10 X 12 INS.		N. AND E.	3 FT.
NI	27"	MOUND OF STONE		3 FT.	1 FT.	SOUTH	ALONGSIDE
OI	24"	3 1/2 IN. IRON PIPE	3 FT.	6 FT. LONG		NORTH	3 FT.
PI	27"	STEEL FENCE POST	2 1/2 FT.			NORTH	3 FT.
QI	28"	STEEL FENCE POST	3 FT.			NORTH	3 FT.
RI	27"	STEEL FENCE POST	3 FT.			NORTH	3 FT.
SI	28"	STEEL FENCE POST	3 FT.			NORTH	3 FT.
TI	22"	MOUND OF STONE		3 FT.	6 INS.	ENCIRCLING MONUMENT	
UI	27"	STEEL FENCE POST	3 FT.			SE. ON LINE	9 FT.

MEANDERS TRACT H

Along a well-defined bank  
of the line of mean high tide.

1. S. 30°14' E., 120.53 ft.
2. N. 68°11' E., 110.03 ft.
3. N. 29°17' E., 65.35 ft.


CENTERLINE TRAVERSE OF  
ACCESS EASEMENT FOR TRACT H

1. S. 68°00' W., 15.04 ft.
2. S. 42°59' W., 47.42 ft.
3. S. 59°25' W., 93.73 ft.
4. S. 35°27' W., 32.05 ft.
5. S. 71°04' W., 42.45 ft.
6. N. 78°27' W., 50.13 ft.
7. S. 6°31' W., 26.06 ft.
8. S. 42°47' W., 32.50 ft.
9. S. 42°47' W., 57.64 ft.
10. S. 61°33' W., 32.61 ft.
11. S. 1°00' W., 52.11 ft.
12. S. 63°44' W., 150.40 ft.


- LEGEND**
- Set a stainless steel post, 2 1/2 ins. diam., 28 ins. long, with brass cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, and adjoining survey lines and numbers. Witness corner to meander corners have additional marks WC MC. Refer to Monument and Accessory Table for accessories established at each monument. Deposit a magnet in a white plastic case at the base of each stainless steel post.
  - Set a rebar, 5/8 in. diam., 30 ins. long, with aluminum cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, easement lines and adjoining survey lines and numbers. No accessories taken.
  - BLM corner recovered this survey.
  - 2 in. diam. iron pipe with brass cap recovered this survey.
  - 5/8 in. diam. rebar with alum. cap mkd. ADA 500 RT & 73 DLL recovered this survey.
  - 5/8 in. diam. rebar with plastic cap mkd. AKDOT recovered this survey.
  - 5/8 in. diam. rebar with no cap recovered this survey.

True Meridian


Mean Magnetic Declination 19° E.



Found an alum. rod, 3/4 in. diam., firmly set, flush with the ground, with alum. cap mkd. as shown.




Found the original granite stone, 6 x 6 ins. exposed, mkd. KRF CO V on the E. side, and an iron pipe alongside, 1 in. diam., firmly set, projecting 4 ins. above ground, and also an iron pipe alongside, 3 ins. diam., firmly set, projecting 12 ins. above ground, with no marks, with an alum. rod, 3/4 in. diam., firmly set, projecting 2 ins. above the top from inside of the iron pipe, with alum. cap mkd. as shown.



Found an iron pipe, 3 1/2 ins. diam., firmly set, broken flush with the ground, and an alum. rod, 3/4 in. diam., firmly set, projecting 2 ins. above the top from inside of the iron pipe, with alum. cap mkd. as shown.


The remains of an original pit, 12 x 12 x 3 ins., 5 ft. SW. of cor.



Found an iron pipe, 3 1/2 ins. diam., firmly set, broken off flush with the ground, with fragmentary punch marks visible on the side of the top half and an X on the screw cap top.

At the corner point, set a stainless steel post, 2 1/2 ins. diam., 28 ins. long, flush with the ground, through the center of the bottom half of the original iron pipe, mkd. as shown.

Bury the top half of the original iron pipe alongside, inverted.



Found an iron pipe, 3 1/2 ins. diam., firmly set, broken off flush with the ground, with punch marks S2006 COR3 visible on the side of the top half, and an X on the screw cap top, and an alum. rod, 5/8 in. diam., projecting 1 in. above and from inside the iron pipe, with an alum. cap mkd. as shown.

The original pits, 18 x 18 x 5 ins., 7 ft. NE and SE of the cor., on line.

TRACT D  
SEE SHEET No. 7

U.S.S. 162

U.S.S. 2006

TRACT F  
23.16

TRACT E  
4.01

TRACT G  
14.95

TRACT C  
SEE SHEET No. 5

Found an iron pipe, 3 1/2 ins. diam., firmly set, broken off flush with the ground, with punch marks S2006 COR4 on the side of the top half, and an X on the screw cap top.


At the corner point, set a stainless steel post, 2 1/2 ins. diam., 28 ins. long, 27 ins. in the ground, with brass cap mkd. as shown.

Bury the original cor., in 2 pieces alongside, inverted.

Drive a steel fence post, 6 ft. long, 3 ft. in the ground, 2 ft. W. of cor.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Found a stainless steel post, 2 1/2 ins. diam., firmly set, 6 ins. below the westerly edge of a gravel road, with brass cap mkd. as shown.



COPY

2000-3  
Kodiak

ORIGINAL

Sheet 7 of 8 Sheets

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)

KONIAG, INCORPORATED  
AT  
KARLUK, ALASKA

REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

LEGEND

- Set a stainless steel post, 2 1/2 in. diam., 28 in. long, this survey. See sheet No. 6 for monumentation information.
- Set a rebar, 5/8 in. diam., 30 in. long, with aluminum cap mtd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, lot lines, easement lines, and adjoining survey lines and numbers. Witness corner to meander corners have additional marks WC MC. No accessories taken.
- ⊙ BLM corner recovered this survey. See sheet No. 6 for recovery information.

SEE SHEET No. 8  
U.S.S. 2030

U.S.S. 469  
TRACT A

MEANDERS TRACT D



Along a well-defined bank  
at the line of mean high tide.

- LOT 1  
1. S. 86°32' W., 8.71 ft.  
2. N. 86°17' W., 97.25 ft.  
3. N. 57°09' W., 162.49 ft.
- LOT 2  
1. N. 57°09' W., 52.99 ft.  
2. N. 41°11' W., 24.67 ft.
- LOT 3  
1. N. 41°11' W., 60.81 ft.
- LOT 14  
1. N. 55°35' W., 71.31 ft.  
2. N. 84°25' E., 40.57 ft.  
3. S. 78°23' W., 73.97 ft.  
4. S. 86°32' W., 67.45 ft.

Mean  
Magnetic  
Declination  
19° E.

NOTE:

The seasonal creeks segregating lots 16 and 17  
and a portion of lots 6 and 8, are measured  
to the thread and are ambulatory boundaries.



COPY

LEGEND

○ Set a rebar, 5/8 in. diam., 30 ins. long, with aluminum cap mkd. ANCSA 14(C) KIK 1998 and with the appropriate tract letters, tract lines, easement lines, and adjoining survey lines and numbers. No accessories taken.

● BLM corner recovered this survey.

E2

Found a basalt stone, 8 x 12 x 16 ins. high, 3 ins. exposed, lying horizontal on E. side, mkd. X on top, and CI S2030 on the side.

Reset the stone to show 3 ins. above ground.

No evidence of the original pits, no new accessories taken.

Deposit a magnet in a white plastic case at the base of the original basalt stone.

F2

Found remains of a concrete filled iron post, 1 in. diam., firmly set, projecting 1 in. above ground, surrounded by 3 stones, with no cap.

At the corner point, set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, encircled by a mound of stone, 2 ft. base, to top of brass cap mkd. as shown.

Bury the original concrete filled iron post inside of the stainless steel post.

No accessories taken.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

G2

Found an iron pipe, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd. as shown.

Drive the original iron pipe to show 1 in. above ground.

No accessories taken.

H2

Found a granite boulder, 4 x 8 x 18 ins., flush with the ground, mkd. X C on top and S2030 visible on the side.

No accessories taken.

Deposit a magnet in a white plastic case at the base of the original granite boulder.

I2

Found a basalt stone, 12 x 6 x 12 ins. high, flush with the ground, with an X on top and C5 S2030 on the sides.

No evidence of the original pits, no new accessories taken.

Deposit a magnet in a white plastic case at the base of the original granite stone.


J2

Found a basalt stone, 8 x 8 x 6 ins. exposed, mkd. X on top and RGM C-1 visible on the sides.

The remains of an original pit, 18 x 18 x 3 ins., 6 ft. SE of cor., on line.

No new accessories taken.

Deposit a magnet in a white plastic case, on the E. side of the original basalt stone, 12 ins. deep.



This cor. is determined at the found position of the original glass memorial, 20 ins. below ground; no remaining evidence of the original iron pipe.

The original pits, shallow depressions, 12 x 12 x 4 ins., NE and SE, on line, 6 ft. dist.

No remaining evidence of the original mound of earth.

At the corner point, set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., flush with the ground, with brass cap mkd. as shown.

Rehabilitate the original pits to now measure 18 x 18 x 12 ins., NE and SE, on line, 6 ft. dist.

Deposit the original glass memorial and a magnet in a white plastic case at the base of the stainless steel post.

L2

Found an iron pipe, 4 ins. diam., firmly set, projecting 12 ins. above ground, with punch marks RGM TA Cor. 3. on the side.

The original pits, shallow depressions, 12 x 12 x 3 ins., NE and NW, on line, 6 ft. dist.


Cor. is surrounded by graves.

No new accessories taken.

M2

Found a severely rusted iron pipe, 4 ins. diam., firmly set, projecting 14 ins. above ground, with punch marks Cor. 4 faintly visible on the side, and an alum. rod, 3/4 in. diam., firmly set, flush with the top of and driven through the center of the original iron pipe, with alum. cap mkd. as shown.

No remaining evidence of the original pits and mound of earth, no new accessories taken.



2000-3

RECORDED FILED

Index

2/9 2000

2:47 P.M.

Revised by BLM

ALASKA NATIVE CLAIMS SETTLEMENT ACT  
(ANCSA) SECTION 14 (C) TRACTS A THROUGH H  
P.L. 92-203, (85 STAT. 688, 702, 703)



KONIAG, INCORPORATED

AT

KARLUK, ALASKA

REFERENCE SHOULD BE MADE  
TO  
SHEET No. 1  
FOR SURVEY INFORMATION

SEE SHEET No. 7



COPY